

List of Technical Articles in Bodacious

Cylinders	Model relevance	Category	Subjects	Edition	Pages
6	400 - 406	Parts	Water-pump impellers and T'stat housings (Jan 11	8
6	400 -406	Engine	6-cyl rocker box oil seals	Mrz 11	7
6	400 - 406	Transmission	Overdrive engagement switching	Mrz 11	6 & 7
6	403	Model	The 403	Jul 11	18 & 19
6	400 - 406	Carburation	Imroving 6-cyl carburation	Nov 11	29 & 30
6	406	Electrical	406 (roof) indicator repeaters	Nov 11	26 - 28
6	400 - 406	Engine	Engine, g/box, torque and rocker rubbers	Nov 11	29
6	400 - 406	Fuel system	Fuel pump improvements (6-cy)	Nov 11	31
6	400 - 406	Electrical	Spark plugs for 2-litre engines	Jul 12	32 & 33
6	400 - 406	Electrical	Xenon lights for 6-yl	Jul 12	33 & 34
6	400 - 406	Engine	Pre-engaged Starters (6-cyl)	Jul 12	29 - 31
6	400	Model	Refurbishing a 400	Sep 12	21 -24
6	400-406	Transmission	1st-gear synchro conversion (6-cyl)	Nov 12	21
6	400 - 406	Transmission	Installing pre-engaged starter motors (6-cyl)	Nov 12	23 - 27
6	401 - 403	Glazing	Leaky 401 Windscreen	Jan 13	16
6	412 & Beaufighter	Model	Bristol 412	Jan 13	7-13
6	400 - 406	Electrical	Ignition timing 6-cyl	Mrz 13	16 (18)
6	400 - 406	Engine	Valve clearance 6-cyl	Mrz 13	15 (16)
6	400 - 406	Transmission	2-litre Gear-box Mountings	Mrz 13	25 - 27
6	400-406	Electrical	Alternator conversion for 6-Cyl Cars	Jul 13	24 - 25
6	400 - 406	Carburation	Maintaining and tuning 6-cylinder cars	Sep 13	22-26
6	400 - 406	Transmission	Overdrive rear seal replacement - 406	Jan 14	22-25
6	400 - 406	Transmission	2-litre gearbox removal	Apr 14	32-37
6	400 - 406	Engine	Timing chain rubbing block installtion -2-litre	Jan 15	28 & 29
6	400 - 405	Structure	Steam-bending and lamination of ash fames	Jan 15	14-15
6	401-403	Transmission	Stress-cracking of 400-403 Axle casings - Par	Jan 15	22-27
6	401-403	Transmission	Stress-cracking of 400-403 Axle casings - Par	Mrz 15	22-29
6	401-403	Transmission	Stress-cracking of 400-403 Axle casings - Par	Mai 15	34 & 35
6	404 - 406	Carburation	Solex triples for 406 Part 1	Sep 15	26 - 28
6	404 - 406	Carburation	Solex triples for 406 Part 2	Nov 15	26 & 27
6	401-404	Glazing	401/3 Rear Screens	Nov 15	26
6	401-403	Transmission	Clutch mechanism repairs 401/3	Nov 15	22-24

List of Technical Articles in Bodacious

6	404 - 406	Carburation	Solex triples for 406 Part 3	Jan 16	25-27
6	401-406	Suspension	ENOTS One-shot chassis lubrication system	Jan 16	20 - 24
6	400 - 406	Special Tools	Exhaust nut spanner	Mrz 16	14
6	400 - 406	Engine	Replacement of 2 litre engine mounts	Mrz 16	22 & 23
6	400-406	Transmission	Differential Buzz	Mai 16	9 & 10
6	400-406	Parts	Oil pressure relief valve springs and seating	Mai 16	12
6	400 - 406	Steering	Replacing Steering Joint Doughnut	Jul 16	25 & 26
6	404	Model	Restoration - structural	Sep 16	12 & 13
6	405	Glazing	405 quarterlight seals	Nov 16	11
6	401/3	Parts	Door push button rubber seals	Nov 16	17
6	400	Parts	Jaking point rubber surround	Nov 16	17
6	400	Parts	Windscreen wiper gromets	Nov 16	17
6	401 & 405	Parts	Bristol Coachwork badges	Nov 16	17
6	404	Model	Restoration - Engine rebuild	Nov 16	20, 21 & 27
6	404	Model	Restoration - body	Jan 17	10 & 11
6	400 - 406	Exhaust	New design C-spanner	Mrz 17	20
6	400-403	Transmission	Gear lever boots (original & remote)	Mrz 17	23
6	400	Coachwork	Boot rubber seal	Mrz 17	23
6	401	Coachwork	Bulkhead and Windscreen rubber seals	Mrz 17	23
6	401/3	Coachwork	Body/bumper and Door/Quarterlight rubber	Mrz 17	23
6	401-2-3	Suspension	Shock absorbers for Aerodynes	Mrz 17	27 & 28
6	400 - 406	Carburation	2-litre fuel consumption	Jul 17	5
6	401	Transmission	Wiring an Overdrive	Jul 17	18 & 19
6	400 - 406	Suspension	2-litre suspension gaiters	Win-17	16 & 17
6	400 - 406	Carburation	Bristol 6-port head	Win-17	22
6	400 - 406	Suspension	2-litre suspension gaiters - update	Spr-18	11
6	406	Glazing	Windscreen development	Sum-18	6 & 7
6	400-406	Transmission	2-litre pre-engaged starter motors	Sum-18	9
6	405	Brakes	406 Disc brakes	Aut-18	6 & 7
6	400 - 406	Carburation	Tuning Solex Carburettors	Win-18	9 - 11
6	406	Glazing	406 windscreen developments	Win-18	12
6	400 -406	Engine	Engne test cards	Win-18	24 - 26
6	403	Model	Restoration update	Spr-19	8 - 10

List of Technical Articles in Bodacious

6	403	Brakes	403 Brake trials	Spr-19	11 & 12
6	400-406	Parts	Obstruction spanner for 6-cyl head nuts	Spr-19	12
6	403	Model	Restoration update	Sum-19	8 & 9
6	406	Glazing	406 Windscreen development - The end!	Sum-19	10 - 13
6	403	Model	Restoration updte - Engine	Aut-19	8 - 10
6	406	Transmission	406 Synchromesh installation	Aut-19	11 - 13
6	400 - 406	Engine	Valve stems seals	Aut-19	14 - 17
6	403	Brakes	Brake shoe steady springs	Win-19	8 & 9
8	407 - 410	Electrical	Indicator switches - 407 - 410	Jan 11	5
8	407 - 411 S1	Parts	Brake and suspension parts - 408 Mk II	Jan 11	8
8	407 - Brigand	Electrical	Headlamp flash and cooling fans	Jul 11	25 - 27
8	407 - Brigand	Fuel system	LPG/Aoutogas conversions (V8)	Jul 11	30 & 31
8	409	Transmission	409 Wheels	Jul 11	22 & 23
8	407 - Blenheim	Electrical	V8 electrical components	Nov 11	30
8	Blenheim	Model	The Blenheim	Nov 11	16 - 21
8	411 - 603	Transmission	Tyres for the 411, 412 and 603	Mrz 12	35 - 37
8	407 - Brigand	Parts	Hub cap, bonnet and boot badges (V8s)	Mai 12	30
8	409	Transmission	409 Wheels	Mai 12	16 & 21
8	407-409	Transmission	Tyre choices for 408	Mai 12	32 - 34
8	407 - Blenheim	Parts	V8 Parts sources	Nov 12	21
8	407 - Blenheim	Engine	Blown Head Gaskets (V8s)	Mai 13	25
8	407 - Brigand	Transmission	Torqueflite (3-sp) Renovation (V8s)	Mai 13	11 & 31
8	407 - 603	Suspension	Replacing the dampers on 411 S3	Mai 14	22-26
8	407 - Brigand	Suspension	Adjusting V8 Camber	Sep 14	27 - 29
8	407 - 603	Cooling	Two-speed cooling fans for V8s	Nov 14	22-25
8	407 - Blenheim	Electrical	Coils for V8s and Starting Problems	Jul 15	32 & 33
8	Turby	Exhaust	Stainless Steel Exhausts for Bristol Brigand	Jan 16	12 & 13
8	407 - Blenheim	Exhaust	Silencer Heat Shields	Mai 16	8
8	407 - Blenheim	Electrical	Wiring diagrams	Jan 17	25
8	410	Interiors	Front seat squab	Jan 17	26
8	407-Blenhiem	Model	Parts sources	Sum-18	8
8	407 - Blenheim	Transmission	Torqueflite autobix repairs and servicing	Aut-18	7
8	603	Coachwork	Bristol 603 Bumpers	Aut-18	8 & 9

List of Technical Articles in Bodacious

8	411	Coachwork	Inner driving lamp surrounds	Win-18	13
8	407 - Brigand	Electrical	Heater blower resistance	Sum-19	14
8	408	Brakes	Source	Sum-19	14
8	407 - Brigand	Engine	Top and Bottom hoses	Sum-19	14
6 & 8	406 & 407	Parts	406/407 Hubcap Buffer Rubbers	Mrz 16	12 & 13
6 & 8	406 -411 S5	Parts	Door window frame reaction rubbers	Mrz 16	20
6 & 8	406 -411 S5	Parts	Door chrome frame seal	Mrz 16	20 & 21
6 & 8	406 - 411 S5	Parts	Outside Chrome Door Handle Gaskets	Mai 16	12
6 & 8	406 - Blenheim	Suspension	Rear Ride Height	Jul 16	22 & 23
6 & 8	400 - Brigand	Parts	Handbrake rubber boots	Nov 16	17
6 & 8	400 - Brigand	Parts	Flexible oil retainers for rear-suspension swi	Nov 16	17
6 & 8	400 - Brigand	Parts	Draught excluder for steering colum at bulk	Nov 16	17
6 & 8	400 - 603	Electrical	Headlamps	Mrz 17	22
6 & 8	400 - 603	Parts	Stainless steel bumper bolts	Sum-18	8
6 & 8	405 - Blenheim	Coachwork	Carriage ock T keys	Aut-18	9
6 & 8	406 - Fighter	Brakes	Disks	Win-18	8 & 9
6 & 8	406 - Fighter	Brakes	Brake Discs	Spr-19	14 & 15
6 & 8	406 - 411S5	Glazing	Winscreen seals	Aut-19	21
6 & 8	406 -411 S5	Glazing	Fitting windscreens	Win-19	12 - 13
8 & 10	Blenheim & Fighter	Electrical	Future Electrical Component Shortages	Mai 16	18
All	400 -Blenheim	Coachwork	Capive nut assembly	Jan 11	6
All	405 - 411 S2	Coachwork	Door handles 405 - 411 S2	Jan 11	7
All	400 - Blenheim	Parts	Winscreen rubbers	Jan 11	9
All	400 - 411 S4	Coachwork	Hub caps	Mrz 11	8
All	400 - Fighter	Engine	6-cyl engine removal	Mrz 11	6
All	400 - Fighter	Interiors	Carpets	Mrz 11	8
All	406 - 603	Model	Refurbishing a 411 Part 1	Mrz 11	22 & 23
All	400 - Fighter	VALUES	Bristol car prices	Mrz 11	24 & 25
All	400 - Blenheim	Electrical	Relays etc Part 1	Mai 11	17 - 19
All	400 - Fighter	Insurance	Multi-vehicle insurance	Mai 11	11
All	400 - Blenheim	Structure	Refurbishing a 411 Part 2 - chassis repair	Mai 11	20 & 21
All	400 - Blenheim	Transmission	Rear axle oil leaaks	Mai 11	22 - 26
All	400 - Blenheim	Electrical	Relays etc.- continued - Ignition switch	Jul 11	24

List of Technical Articles in Bodacious

All	400 -Blenheim	Glazing	Windscreens	Jul 11	28 & 29
All	400 - Blenheim	Coachwork	Restoring a 411 Pt 3 - Alumium repairs	Nov 11	23 & 24
All	404 - 411 S2	Coachwork	Door hndles 404 - 411 S2	Nov 11	28
All	404 - 603	Glazing	Windscreen rubbers 406 - 603	Nov 11	28
All	404 - 411 S5	Glazing	Front and rear screen removal (406 - 411 S5)	Jan 12	35
All	400 - 408 MkI	Steering	Power assisted steering (pre-408 Mk II)	Jan 12	36 & 37
All	400 - Blenheim	Interiors	Veneer refurbishment	Mrz 12	31 - 34
All	400 - Blenheim	Parts	Initial parts list	Mai 12	30 - 31
All	400 - Brigand	Engine	Screw Thread definitions	Jul 12	28
All	400 - Blenheim	Parts	Door & 1/4-light seals and starter rings avail:	Jul 12	29
All	400 - Brigand	Electrical	Smiths instruments	Sep 12	14 - 16 & 21
All	400 - Brigand	Carburation	Charging Carburettors by Electric Pump	Jan 13	22
All	406 - Brigand	Electrical	Winscreen wiper mechanism 411	Jan 13	26
All	406 - 411 S5	Glazing	Rear Quarter Widnows 411	Jan 13	24
All	406 - Brigand	Interiors	Removing the internal trim 411	Jan 13	23
All	406 - Blenheim	Interiors	Dismantling the doors 411	Jan 13	24 - 26
All	404-408	Structure	Fitting seat belts in a 406	Mai 13	20-24
All	406 - 411 S5	Cooling	Improve your cooling - front valance closer p	Jul 13	20 - 23
All	406 - 411 S5	Glazing	Fitting 406 Windscreens	Nov 13	24-27
All	405 - Brigand	Electrical	V8 Rotary and Rocker Switch Overhaul	Jul 14	28-29
All	406 - 603	Structure	Fabricating front chassis legs and closing pla	Jul 14	24-27
All	400 - Fighter	Model	Trailing your Classic - (New) Rules	Mai 16	19 & 21
All	400 - Fighter	Engine	Reasons for warmng up cars	Sep 16	27 & 28
All	400 - Blenheim	Structure	Door and hinges removal	Sep 16	29 - 33
All	400 - Blenheim	Parts	Captive nut assemblies	Jan 17	20
All	400 - Fighter	Electrical	LED lights	Jul 17	20 - 22
All	400 - Fighter	Model	Modifications or Sensible Changes	Win-17	18 - 19
All	400 - Fighter	Interiors	Trimming	Spr-19	13 & 14
All	400 - Blenheim	Glazing	Wiper arms and blades source	Sum-19	14
All	400 - Fighter	Electrical	Ignition leads	Sum-19	14 - 17
All	400 - Brigand	Electrical	Smiths clocks	Win-19	10 & 11
All	400 - Blenheim	Perts	Restoration parts sourcing	Win-19	14 - 17